Presented by
Peter Herzog
Herzog/Wheeler & Associates LLP
St. Paul, MN
March 16, 2006

Information derived from

"Methods to Improve Preservation Management in Libraries, Museums and Archives"

By James Reilly, IPI Rochester Institute of Technology

Optimization:


"A process designed to ensure that each preservation environmental control (HVAC) system continually provides the best environment it is capable of, a the least possible energy use."

Research Questions:

- 1. What climate is the existing system capable of delivering on an annual basis?
- 2. What climate is the existing system actually delivering on an annual basis?
- 3. Is the system consuming more energy than necessary to deliver the actual climate?
- 4. What procedures would ensure continual optimal operation?


Research Tasks:

Document
 System
 Configuration




Research Tasks:

2. Measure
System
Performance




Research Tasks:


3. Measure Collection Climates



Research Tasks:

4. Analyze the Data Collected





Findings:

Sub-optimal Condition:

Storage space warmer than necessary


Causes:

Inappropriate set point selection


Supply air set point increased due to occupant complaint

Supply air set point inexplicably increased Winter control schedules operating in summer Reheat coil malfunctions

Unexplained Set Point Changes



Winter Control Schedule in Summer



Findings:

Sub-optimal Condition:


Storage space more humid than necessary

Causes:

Malfunctions in chilling system, resulting in elevated dew point temperature

Insufficient reheating

Malfunction in chilling system



Findings:

Sub-optimal Condition:


Storage spaces drier than necessary

Causes:

Insufficient maintenance of humidifier

Humidifier disabled

Storage Space Drier than Necessary





Findings:

Sub-optimal energy performance:


- Unnecessary sub-cooling and reheating
- Excess preheating of outside air
- Underutilization of variable speed drives on supply fans
- Unnecessary operation of space lighting

Unnecessary Sub-Cooling and Reheating







Outside Air Dew Points





Underutilized Variable Speed Drive






Energy Costs Savings Opportunities





People Who Affect Collection Climates



Recommendation:

Form a Preservation Environment Management Team Responsible for:

- 1. Documenting Systems' Configuration & Capabilities
- 2. Negotiating Climate Goals
- 3. Measuring Actual Performance
- 4. Quickly Correcting Sub-Optimal Performance

