

25 Sept 64

25 SEP 64 R 739

TO : MEXICO CITY
FROM : DIRECTOR
CONF: TSD 6
INFO: WHY CI, CI/OPS, FI, UK

Bustos

DEFERRED
ROUTINE

TO PRIORITY MEXI INFO

CITE DIR 52651

AQUATIC LIONION
REF MEXI 0982 (IN 79741)*

1. PULSE CAMERAS BEING MODIFIED AND RECONDITIONED BY CONTRACT TO CORRECT FAULTS SURFACED DURING LIONION OP. ~~MINIMUM TIME OF~~ AVAILABILITY FIRST CAMERA THREE WEEKS PROVIDING NO UNFORESEEN DIFFICULTIES OCCUR.
2. IF PRESENT CAMERA INOPERABLE SUGGEST RETURN TO ROBOT AND VLS-2 OR K-100 WITH BURST BRACKET AND VLS-2 FOR INTERIM OPERATIONAL COVERAGE.
3. A SECOND CAMERA WILL BE SENT MEXI AS SOON AS RECONDITIONING COMPLETED FOR USE STANDBY.

- END OF MESSAGE -

TSD/COMMENT: *LIONION pulse camera malfunctioning.
Request Hq forward replacement.

*Lionion
Request*

W/L/Mexico Miss Bustos by phone x4523

[Signature]

TSD/FPB Mr. [] in draft

SEYMOUR MUSEL
C/TSD
RELEASING OFFICER

COORDINATING OFFICERS

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

C/TSD/OA
AUTHENTICATING
OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy