Date:

9/21/201

Agency Information

AGENCY:

HSCA

RECORD NUMBER:

180-10080-10168

RECORD SERIES:

NUMBERED FILES

AGENCY FILE NUMBER:

008590

Released under the John

⁷. Kennedy

Assassination Records Collection Act of 1992

(44 USC 2107 Note). Case#:NW 56829 Date:

04-13-2018

Document Information

ORIGINATOR:

NASA

FROM:

CANNING, THOMAS N.

TO:

GOLDSMITH, MICHAEL

TITLE:

DATE:

04/19/1978

PAGES:

SUBJECTS:

KENNEDY, JOHN; ASSASSINATION

EVIDENCE

DOCUMENT TYPE:

LETTER

CLASSIFICATION: RESTRICTIONS:

Unclassified

Consulted

CURRENT STATUS:

Withhold

DATE OF LAST REVIEW:

07/24/1993

OPENING CRITERIA:

COMMENTS:

List of repairs and modifications to presidential limousine. Box 156.

1

National Aeronautics and Space Administration

Ames Research Center Moffett Field, California 94035



008590

Reply to Attn of: TC:244-7-57

April 19, 1978

Mr. Michael Goldsmith House Select Committee on Assassinations 3331 House Office Bldg., Annex 2 Washington, D.C. 20515

Dear Mike:

During the March meeting of the Photographic and Forensic Pathology meetings, I requested that a detailed listing of minor and major repairs and inspections of the trunk area of the Presidential limousine (done after the assassination) be provided.

The listing (which is returned herein) predates the assassination by two years and cannot be of use. My interest continues in the post-assassination inspections, cleanup and repairs of the trunk-spare tire area. Please provide the records, if available.

Sincerely,

Thomas N. Canning

Enclosure: As stated

Lee Fallins 313-322-8740-1

September 13, 1961

Mr. Max L. Westbay Experimental Parts Section and a Parts 1 Address to the parts that the section of the Parts of t Purchasing Office Ford Motor Company P. O. Box 623 Dearborn, Michigan

entry of the last the second Charles Bertall (\$1) die stein

> SUBJECT: 1961 Presidential Lincoln Continental Modification

er svener i kali i med kali kali sa mengala s

Dear Max:

In reply to your request for a quotation for modification work on the 1961 Presidential Lincoln Continental, we submit the following outline of work included in this quotation.

Center Gody Pillar

Redesign and fabricate the upper glass frame and pillar assembly to allow it to be fully removed. Fabricate new upper pillars. Provide new glass. Fabricate new glass frames and the management of the contract The state of the s Install new weatherstrip Rework lower pillar area, design and fabricate anchoring device. Provide for anchor and detachable clamps for center body pillar cross bar.

Center Body Pillar Cross Bar

Redesign the bar to allow it to be fully removed when center body pillar upper glass frames are removed. Rework cross bar, machine ends, install locating pins or blocks and replate. Provide quick acting clamps.

entitle at a regulation to have the series when the series

Bushali (1904) Princes and which to tobe according

Limousine Partition Glass with a recommon but workers

D-Z MODIFICATION Brown to easily in the most electrical of their court him is and

· 第二十二 化氢素酸 "\$P"的 清朝 "那\$P" 海的电路像一层像

September 13, 1961

His septe a proper in the second of the

Mr. Max L. Westbay Dearborn, Michigan

Page two

With the U

4. Front Seat Top Bar

Fabricate, leather trim and install to conceal partition glass opening.

The second residual to the second second

5. Front Seat Grab Handles

Design, fabricate and install two chrome plated grab handles on top bar of front seat.

6. Rear Seat Cushion

Build up experimental seat cushion pad to open seat included angle and to provide differential deflection in specific areas.

Untrim rear cushion and rebuild to above approved pad. Install special Ensulite pads and retrim.

7. Rear Floor Fillers

Make up and install rear floor fillers under rear floor carpet to remove 6° slope from center tunnel to rocker sill.

Rework and refit carpet. The Ball with paint All the State of the Control of the

8. Rear Seat Cushion - Arm Rest

Design and fabricate rear seat cushion arm rest.
Weight arm rest with sea sand and trim in leather.
Arm rest is a loose unit and may be carried in trunk when not required.

9. It Robe Straps in a glader and less derivited gains to the beganning

Design, fabricate and install elastic cords or straps to retain robe neatly in rear side door robe pockets.

10. Bumper Guard and Red Lights

Rework patterns to meet contour of 1962 front bumper bar. Make up, machine and plate new castings.

Install red lights and mount to 1962 bumper.

Mr. Max L. Westbay Dearborn, Michigan September 13, 1961

Page three

4 . nM.

S 1 18 4 16

الكوارية

.6

.UI

11. Front End Rework

Remove 1961 front end parts, grilles, moldings and bumpers. Install 1962 parts to be furnished by Ford Motor Company. Modify all parts and assemblies as required.

12. Miscellaneous

Clean and touch up sheet metal as required. Rework partition switch escutcheons and electrical circuits as required.

andro an et d'élématique, et la

Our estimated quotation for this work is \$4000.00, plus any local, state or federal tax that may apply.

It is anticipated that the work can be completed in approximately three weeks after receipt of car.

If you have any questions regarding the work outline, we will be happy to discuss them with you.

later man recommend which Very truly yours,

THE HESS & EISENHARDT COMPANY

Vice President in Charge of Manufacturing & Engineering

Willard C. Hess Jes

P. S. This includes engineering and service trip to Washington, D. C. August 29, 30 and 31. Items 3, 4, 6 and 7 were completed in Washington.

cc: Mr. Gordon Doherty

Barry Barry

berause fit up pad enems.

CORP DON'T COMP

- J. T. Kraus
- C. W. Hartline
- A. J. Schaerges

Simple distant

NW 56829 DocId: 32248610 Page 5

C Harthur

Mr. Max L. Westbay Dearborn, Michigan

September 13, 1961

Page four

165

.17

.21

393

uoi.

11: 13:1

91

45

{ **i**‱ |

ζ,

- P. P. S. Additions to 1961 Presidential Continental Modification
- 3. (Cont.) Partition

Remove glass
Retrim No. 2 crossbar
Remove glass drive motors
Remove glass drive channel.

6. (Cont.) Rear Seat Cushion

Remove seat assembly
Untrim rear seat cushion and back
Install 1/4 plywood panel in each as per direction
from V. Ferguson.

13. Rear Canvas Cover

Cut and install vinyl window of formal limousine size.

Paul Character and a consideration of

14. Flag Brackets

Make new retainer nuts.

- 15. <u>Canvas Roof</u>
 Improve fit up and snaps.
- 16. <u>L.H. Rear Door Glass</u>
 Check for cause of scratching.
- 17. <u>Trunk Lid</u>

 Adjust tension hold open.
- 18. Rear Seat Pump
 Check gasket.

WCH: Jes cc: J. T. Kraus C. W. Hartline

PROJECT D-2 DRAWINGS BEING SENT OUT

Fo. Mo. Co

| 1000 | 1 11 | r fr | LER FOLLINS |
|--------|------|--------------------|---|
| Drg. | Size | Part No. | Description |
| Ε | | EX-5500 | BODY DRAFT |
| Ē | | EX-5502 | PRELIMINARY LAYOUT (REAR END & REAR ROOF) (FOR MOCK UP) |
| Ē | | | CONTINENTAL TIRE KIT INSTALLATION (2 SHEETS) SHT 1 42" WIDE FILLED W/DR |
| Ē | | EX-5504 | REAR BUMPER ASSEMBLY |
| Ā | | EX-5506 | |
| Α | | EX-5507 | n e e e e e e e e e e e e e e e e e e e |
| A | | EX-5508 | 11 |
| Ε | | EX-5510 | PLASTIC ROOF ASSEMBLY |
| Α | | EX-5511 | PLATE-REAR DOOR SILL |
| Α | | EX-5512 | INSERT-REAR DOOR SILL PLATE |
| С | | EX-5513 | PANEL-REAR DECK LID CONTINENTAL TIRE COVER |
| C | | EX-5514 | PANEL-REAR CONTINENTAL TIRE COVER |
| В | | EX-5515 | STIFFENER ASSY-FLOOR SIDE OUTER MEMBER |
| В | | EX-5516 | EXTENSION-FLOOR SIDE INNER MEMBER |
| В | | EX-5517 | EXTENSION-FLOOR SIDE LOWER MEMBER |
| . E | | EX-5519 | MEMBER ASSY-CENTER BEARING FLOOR PAN CROSS MEMBER "A" |
| See | 5519 | EX-5520 | MEMBER ASSY-CENTER FLOOR PAN CROSS MEMBER "B" |
| Α | | EX-5521 | STRAP - RESONATOR INLET PIPE MOUNTING |
| Α | | EX-5522 | CLIP-PARKING BRAKE CABLE SUPPORT |
| E | | EX-5523 | PAN-CENTER FLOOR |
| Ε | | EX-5524 | PRELIMINARY STUDY OF FRT SEAT GUN COMPT & PARTITION |
| Α | | EX-5526 | BRACKET-FUEL FILTER TO A.C. BRKT |
| В | | EX-5527 | RAIL-CTR BODY PILLAR BELT |
| E | • | EX-5528 | EXTENSION-CTR BODY PILLAR FRONT |
| E | | EX-5529 | EXTENSION-CTR BODY PILLAR REAR |
| В | | EX-5530 | REINFORCEMENT-CTR BODY PILLAR BELT RAIL |
| С | | EX-5531 | PANEL-CTR BODY PILLAR UPPER OUTER |
| E | | EX-5532 | PANEL-CTR BODY PILLAR LOWER OUTER |
| В | | EX-5533 | STRAP-ALTERNATOR BELT TENSION |
| С | | EX-5534 | BRACKET-ALTERNATOR (ON ALTERNATOR) |
| В | * | EX-5535 | BRACKET-ALTERNATOR (ON ENGINE) |
| E | | EX-5536 | GLASS-REAR DOOR WINDOW |
| D | | EX-5537 | CTR BODY PILLAR WINDOW ASSY |
| D | 5538 | EX-5538 EX-5539 | CTR BODY PILLAR WINDOW FRAME ASSY-UPPER FRAME-CTR BODY PILLAR WINDOW UPPER |
| | JJ30 | | |
| В | | EX-5540 | RETAINER-CTR BODY PILLAR WINDOW FRAME |
| D A | | EX-5541 EX-5542 | GLASS-CTR BODY PILLAR WINDOW CTR BODY PILLAR WINDOW FRAME ASSY-LOWER |
| | 5542 | EX-5543 | FRAME-CTR BODY PILLAR WINDOW LOWER |
| A | JJ42 | EX-5544 | REINFORCEMENT-CTR BODY PILLAR WINDOW LOWER FRAME |
| Ē. | , | EX-5549 | FRAME-ASSEM FRONT DOOR GLASS |
| E | | €X-5550 | LAYOUT OF CTR BODY PILLAR & PARTITION (2 SHEETS)(SHT 2 42" WIDE W/. DRAFT |
| E | | EX-5552 | FRAME ASSEM-REAR DOOR GLASS |
| D | | EX-5555 | SIDE QUARTER GLASS FRAME ASSEMBLY |
| C | | EX-5556 | GLASS- " " " . |
| | | EX-5557 | REAR SEAT STUDY |
| E | | EX-5558 | GLASS-REAR BACK LIGHT (FORMAL SEDAN) |
| D | | EX-5559 | TRIM SCHEME-SEAT CUSHION PAN |
| E | : | EX-5560 | FOLDING SEAT ASSEMBLY |
| _ | | | . Carrier on it rescribe! |

| Drg. Size | Part No. | Description |
|-----------------------|--|--|
| C A A E C | EX-5561 EX-5562 EX-5563 EX-5564 EX-5565 EX-5566 | PLATE-FLOOR REINFORCING HINGE-FOLDING SEAT FLOOR OUTSIDE PIN-FOLDING SEAT FLOOR HINGE SPACER-FOLDING SEAT FLOOR HINGE PIN FRAME (ASSY) - SEAT CUSHION - L.H. SEAT LEG-FOLDING SEAT OUTSIDE |
| Ď | EX-5567 | PAN-SEAT CUSHION - L.H. SEAT |
| C | | FRAME (ASSY) - SEAT BACK |
| В | | RAIL - SEAT BACK SIDE |
| С | | PAN - SEAT BACK |
| A | EX-5571 | PIN - SEAT BACK HINGE |
| E | | FRAME (ASSY) - SEAT CUSHION - R.H. SEAT |
| C D | | LEG - FOLDING SEAT INSIDE PAN - SEAT CUSHION - R.H. SEAT |
| C | | HINGE - FOLDING SEAT FLOOR INSIDE |
| D | | COVER - SEAT CUSHION PAN TRIM |
| Á | | BAR - CUSHION PAN TRIM COVER ATTACHING TIE |
| D | | PANEL - SEAT CUSHION |
| D | EX-5579 | PAD - SEAT CUSHION |
| | EX-5582 | PAD - SEAT BACK |
| Α | EX-5583 | RISER-SEAT CUSHION PAN TRIM |
| Ε | | PARTITION ASSY |
| | | PANEL-PARTITION (MAIN) |
| A | EX-5589 | STRAINER-PARTITION PANEL (UPPER) |
| See 5589 | | STRAINER-PARTITION PANEL (CTR) |
| See 5589 | | STRAINER-PARTITION PANEL (LOWER) |
| A | EX-5593 | CLOSURE-PARTITION CORNER PANEL (AT BELT) |
| C | | ANGLE-PARTITION ATTACHING PILLAR-CTR BODY UPPER |
| D E | EX-5596 EX-5597 | BOW-CTR BODY PILLAR ROOF |
| В | EX-5598 | CAP-CTR BODY PILLAR FRT (AT BELT) |
| Č | EX-5599 | CAP-CTR BODY PILLAR REAR (AT BELT) |
| В | EX-5600 | RETAINER-CTR BODY PILLAR WEATHERSTRIP |
| See 5585 | | CLOSURE-PARTITION SIDE (AT FLOOR) |
| E | EX-5602 | SCALP-PARTITION GLASS CHANNEL |
| E | EX-5603 | REAR SEAT LAYOUT |
| D | EX-5604 | GLASS-PARTITION |
| E | | FORMAL ROOF ASSEMBLY |
| A | EX-5609 | PLUG-LUGGAGE COMPT. DOOR GRAB HANDLE HOLE (WITH FORMAL ROOF) |
| E | EX-5610 | PROPOSED REAR SEAT AUXILIARY CUSHION (42"WIDE FILLED WITH DRAFT) |
| C C | EX-5611 | LAYOUT OF RADIO & ACCESSORY CONTROLS |
| | EX-5612 | STRAINER-READING LAMP |
| . A | EX-5613 EX-5614 | SHIM-FOLDING SEAT FLOOR OUTSIDE HINGE SHIM-FOLDING SEAT FLOOR INSIDE HINGE |
| A | EX-5615 | SECTION-ROOF RAIL MOLDING PLAST. BLISTER |
| Ā | EX-5616 | SECTION-ROOF RATE MOLDING FLAST, BEISTER SECTION-PLASTIC BLISTER SIDE BELT MOLDING " " |
| . A | EX-5617 | SECTION-PLASTIC BLISTER REAR BELT MOLDING " " |
| . A | EX-5618 | SECTION-REAR ROOF BLISTER FRONT MOLDING " " |
| | | |

| 0 | | |
|------------------|--------------------|---|
| Dr. Size | Part No. | Description |
| · A | EX-5619 | SECTION-REAR SIDE BLISTER INSIDE MOLDING PLAST. BLISTER |
| A | EX-5620 | SECTION-REAR CENTER BLISTER SIDE MOLDING " " |
| Α | EX-5621 | SECTION-CENTER ROOF BLISTER FT & REAR MOLDING " " |
| Α | EX-5622 | SECTION-FORMAL ROOF FRONT FORMAL ROOF |
| E | EX -5625 | REAR ROOF BLISTER FRAME ASSEMBLY |
| A | EX-5626 | ROOF CLAMP ASSY-PLASTIC ROOF & FORMAL ROOF QTR MTG (TO BODY) |
| A, | EX-5627 | ROOF CLAMP ASSY-FORMAL ROOF (REAR) (TO BODY) |
| A | EX-5628 | CLAMP ROOF |
| A | EX-5629 | BASE-ROOF CLAMP-PLASTIC ROOF & FORMAL ROOF QTR MTG |
| A | EX-5630 | BASE-ROOF CLAMP-FORMAL ROOF (REAR) |
| A | EX-5631 | PIN-ROOF CLAMP |
| A A | EX-5632 EX-5633 | ROOF CLAMP & LINK ASSY LINK-ROOF CLAMP |
| Ä | EX-5634 | STRIKER-ROOF CLAMP (REAR DECK) |
| | EX-5635 | STRIKER-ROOF CLAMP (REAR DECK) STRIKER-ROOF CLAMP (PLASTIC ROOF QTR MTG) |
| Ä | EX-5636 | STRIKER-ROOF CLAMP (FORMAL ROOF QTR MTG) |
| C | EX-5637 | FRAME-QUARTER TRIM ESCUTCHEON PANEL |
| See 5637 | | FRAME-L.H. QUAR. TRIM ESCUTCH. PANEL |
| В | EX-5640 | PARTITION CLOCK INSTALLATION PANEL |
| В | EX-5641 | CLOCK BEZEL REOPERATION-PART. CLOCK |
| | EX-5642 | CLOCK HOUSING REOPERATION - PART. CLOCK |
| C | EX-5643 | ENCLOSURE-PARTITION CLOCK |
| Ε | EX-5644 | PANEL-PARTITION CLOCK ESCUTCHEON |
| E | EX-5645 | FRAME-PART. CLOCK ESCUTCHEON PANEL |
| | EX-5646 | PANEL-L.H. QUAR. TRIM PANEL LEDGE |
| В | EX-5647 | REOPERATION OF RADIO BEZEL |
| | | PANEL-L.H. QUARTER TRIM ESCUTCHEON |
| C | EX-5649 | PANEL-R.H. QUARTER TRIM ESCUTCHEON |
| D | | ROOF #1 BOW ASSY & LOCK ASSY LAYOUT |
| D Co. 5/51 | EX-5651 | ROOF #1 BOW ASSY |
| See 5651 | EX-5652 | BOW-ROOF #1 SPACER-ROOF #1 BOW LOCK ASSY |
| A D | EX-5653 EX-5654 | FILLER-ROOF #1 BOW ROOF-FORMAL ROOF |
| A · | EX-5655 | SUPPORT-ROOF #1 BOW LOCKING HOOK PIVOT |
| D | EX-5656 | PANEL-ROOF #1 BOW UPPER (PLASTIC ROOF ONLY) |
| D | EX-5657 | PANEL-ROOF #1 BOW LOWER (PLASTIC ROOF) |
| D | EX-5658 | PANEL-ROOF #1 BOW LOWER (FORMAL ROOF) |
| Α | EX-5659 -B | ROOF #1 BOW LOCK PINION GEAR & STUD ASSY |
| Α | EX-5660-B | |
| Α | EX-5661 | GEAR-ROOF #1 BOW LOCK WORM |
| В | EX-5663 | LUGGAGE COMPARTMENT DOOR GRAB HANDLE BRACKET ASSY |
| S ee 5663 | EX-5664 | BRACKET-LUGGAGE COMPT. DOOR GRAB HANDLE |
| A | EX-5667 | STUD-LUGGAGE COMPT. DOOR GRAB HANDLE BRKT. MTG. |
| * D | EX-5695 | LAYOUT R.H. & L.H. QUAR.PANEL ESCUTCH.PANELS, FRAME, SWITCHES, LEDGES |
| В | EX-5696 | DOOR-R.H. QUAR.PANEL TELEPHONE COMPARTMENT |
| A | EX-5697 | HINGE-R.H. QUAR.PANEL TELEPHONE COMPT. DOOR |
| A | EX-5698 | SPRING-R.H.QUAR.PANEL TELEPHONE COMPT. DOOR |
| A | EX-5699 | PLATE-SWITCH COVER (1-SWITCH FOR L.H. QUAR. PANEL) |
| A | EX-5700 | PLATE-SWITCH COVER (3-SWITCH FOR R.H. QUAR. PANEL) |

| <u>Dr. Size</u> | Part No. | Description |
|-----------------|----------|--|
| A . | EX-5701 | HOUSING-L.H. QUAR. PANEL (1-SW.) SWITCH |
| A | EX-5702 | HOUSING-R.H. QUAR. PANEL (3-SW.) FT. SWITCH |
| Α | EX-5703 | HOUSING-R.H. QUAR. PANEL (3-SW.) CENTER SWITCH |
| Α | EX-5704 | HOUSING-R.H. QUAR. PANEL (3-SW.) REAR SWITCH |
| В | EX-5705 | BAR ASSY-LUGGAGE COMPT DOOR GRAB HANDLE HOLE COVER |
| Α | EX-5706 | SPACER-LUGGAGE COMPT DOOR GRAB HANDLE HOLE COVER BAR |
| Α | EX-5707 | BUSHING-HOLE COVER BAR EXPANDABLE |
| Α | EX-5708 | COVER-GRAB HANDLE RELEASE HOLE (1/2 DIA.) |