

RG 434
Public Involvement Records
Audiovisual Records
Location: 68/8/8

AV Box 1

NRE-434-WS-PHO-0001 Building dismantlement complete, December 8, 1994
NRE-434-WS-PHO-0002 Quarry Bulk Waste Removal 1993-1995
NRE-434-WS-PHO-0003 Building 201 Dismantlement 1993
NRE-434-WS-PHO-0004 January 1994 Activities, Past/Present.
NRE-434-WS-PHO-0005 Remedial Action Project February 1994
NRE-434-WS-PHO-0006 Remedial Action March 1994 Progress
NRE-434-WS-PHO-0007 WSSRAP April 1994
NRE-434-WS-PHO-0008 WSSRAP Activities May 1994
NRE-434-WS-PHO-0009 WSSRAP June 1994 Activities
NRE-434-WS-PHO-0010 Removal of Tributyl Phosphate (TBP) Tanks, July 1994
NRE-434-WS-PHO-0011 Dismantlement of Bldg. 410, August 1994
NRE-434-WS-PHO-0012 Dismantlement of Bldg. 403, September 1994
NRE-434-WS-PHO-0013 Chemical Stabilization/Solidification Pilot Facility, October 1994
NRE-434-WS-PHO-0014 Building 407 Dismantlement, November 1994
NRE-434-WS-PHO-0015 Building Dismantlement Complete, December 1994
NRE-434-WS-PHO-0016 Train 2 of the Site Water Treatment Plant, January 1995
NRE-434-WS-PHO-0017 Quarry Activities February 1995
NRE-434-WS-PHO-0018 Building 434 Improvements March 1995
NRE-434-WS-PHO-0019 New Ponds at Train # 2 April 1995
NRE-434-WS-PHO-0020 Load # 7,500 Milestone Reached May 1995
NRE-434-WS-PHO-0021 Quarry soil sampling and progress June 1995
NRE-434-WS-PHO-0022 PCB Capacitor Removal, Bio Denitrification, 100 Batch Release of treated water
NRE-434-WS-PHO-0023 Tree clearing for CMSA, Railroad Rail Removal, Borrow Area Excavation
NRE-434-WS-PHO-0024 CSS Test Operations September 1995
NRE-434-WS-PHO-0025 Easement Agreement Transaction, Erosion Control Measures, Borrow Area facilities, Borrow Haul Road, October 1995
NRE-434-WS-PHO-0026 Quarry Bulk Waste Removal November 1995
NRE-434-WS-PHO-0027 Slide Gate Installation at Ash Pond, New Staff Gauge in Quarry, Alt. Entrance to Borrow Area, December 1995
NRE-434-WS-PHO-0028 Deheading Operations, Dry Deacon tech. Building Slab Breakup Process, K-25 Pumping Activities January 1996
NRE-434-WS-PHO-0029 Vicinity Property #9 February 1996
NRE-434-WS-PHO-0030 Vicinity Property B-5 March 1996
NRE-434-WS-PHO-0031 Concrete/Rebar Shearing, Underground Storage Tank Removal, Explorer Pipeline installation, Concrete loading April 1996
NRE-434-WS-PHO-0032 Raffinate Pit #4 Debris Consolidation May 1996
NRE-434-WS-PHO-0033 Foundation Removal Process June 1996

NRE-434-WS-PHO-0034 Deactivation of Reactive Metals, Containerized Barium Waste, Silver Contaminated Film Debris Stabilization July 1996
NRE-434-WS-PHO-0035 Raffinate Pit Dredge, Train 2 Brine storage tanks, high school computer donation, public meeting, sludge transfer line, August 1996
NRE-434-WS-PHO-0036 Underground Utility Removal, 2nd Shift Contaminated Soil Removal, Sand Cone Test, Backfill Operation September 1996
NRE-434-WS-PHO-0037 Foundation Removal Activities, Raffinate Pit 4 Activity, October 1996
NRE-434-WS-PHO-0038 Bypass managed by State Hwy Dept., November 1996
NRE-434-WS-PHO-0039 Debris from Pit 4, Oct. 1995, Oct. 1996, December 1996
NRE-434-WS-PHO-0040 Southeast Drainage Contamination Perimeter Survey, MK-F Presents Subcontractor Corvera 360 Day Safety Award, Cons. Of Organic Sludges with Absorbent, Jan. 1997
NRE-434-WS-PHO-0041 Aerial views of Main Site April 1988 and February 1997
NRE-434-WS-PHO-0042 Raffinate Pit 2 Sludge Removal, Chemical Stabilization Solidification Pilot Facility March 1997
NRE-434-WS-PHO-0043 D.H.O Ground Breaking Ceremony April 24, 1997
NRE-434-WS-PHO-0044 Raffinate Pit #4 Debris Consolidation May 1996
NRE-434-WS-PHO-0045 Foundation Removal Process June 1996
NRE-434-WS-PHO-0046 Waste Stream Treatments July 1996
NRE-434-WS-PHO-0047 Raffinate Pit Dredge August 1996
NRE-434-WS-PHO-0048 Foundation Removal Progress September 1996
NRE-434-WS-PHO-0049 Foundation Removal Activities, Raffinate Pit 4 Activity, Oct. 1996
NRE-434-WS-PHO-0050 Bypass Managed by State Hwy. Dept. November 1996
NRE-434-WS-PHO-0051 Raffinate Pit 4 Debris Consolidation Complete December 1996
NRE-434-WS-PHO-0052 Southeast drainage contamination perimeter survey, MK-F Subcontractor Corvera 360 Day Safety Award, Consolidation of Organic Sludges with Absorbent, Jan. 1997
NRE-434-WS-PHO-0053 Aerial View of Main Site April 1988 and February 1997
NRE-434-WS-PHO-0054 Raffinate Pit 2 Sludge Removal March 1997
NRE-434-WS-PHO-0055 D.H.O Ground Breaking Ceremony April 24, 1997
NRE-434-WS-PHO-0056 Work Package 420-Foundations Removal
NRE-434-WS-PHO-0057 Raffinate Pit #4 Sludge Consolidation June 1997
NRE-434-WS-PHO-0058 CSS Production Facility July 1997
NRE-434-WS-PHO-0059 Liner Installation August 1997
NRE-434-WS-PHO-0060 Aerial Sept. 29, 1997, CSS Construction Process, Raffinate Pit 2 Sludge Transfer to Raffinate Pit 3
NRE-434-WS-PHO-0061 Open House Oct. 19, 1997; Cleaning of CAT 637E scraper prior to demobilization, placement of drain gravel, placement of filter sand on layer of drain gravel, installation of 4" perforated pipe for LCRS
NRE-434-WS-PHO-0062 Aerial shots, November 18, 1997
NRE-434-WS-PHO-0063 Remediation of Contaminated Soil at the Army Vicinity Properties, CSS Plan Construction Process December 1997
NRE-434-WS-PHO-0064 MSA Aerial Oct. 1997

AV Box 2

NRE-434-WS-PHO-0065 Aerial Shot
NRE-434-WS-PHO-0066 Weldon Springs Uranium Feed Materials Plant
NRE-434-WS-PHO-0067 Quarry 1993, Three Million Gallons of Water
NRE-434-WS-PHO-0068 Quarry Dump and Cover Operations in the late 50's and 60's
NRE-434-WS-PHO-0069 Debris
NRE-434-WS-PHO-0070 Initial dump and cover operations in the late 50's and 60's
NRE-434-WS-PHO- 0071 Quarry/dump
NRE-434-WS-PHO-0072 St. Charles County Well Field
NRE-434-WS-PHO-0073 Close up Face of Quarry Waste Pile, apx. 100,000 cubic yards
NRE-434-WS-PHO-0074 Weldon Spring Quarry before Cleanup, with water treatment plant outlined, 1988 Quarry Aerial
Photo Missing: Weldon Spring Quarry
NRE-434-WS-PHO-0075 Quarry Water Treatment Plant Construction- Spring '91
NRE-434-WS-PHO-0076 Quarry Water Treatment Plant Liner Installation
NRE-434-WS-PHO-0077 Quarry and Quarry Water Treatment Plant
NRE-434-WS-PHO-0078 Interior of Quarry Water Treatment Plant- August 1994
NRE-434-WS-PHO-0079 Water Treatment System Schematic
NRE-434-WS-PHO-0080 Quarry Water Treatment Plant 1993
NRE-434-WS-PHO-0081 Quarry Pond/Debris
NRE-434-WS-PHO-0082 Weldon Spring Quarry- April 1994
NRE-434-WS-PHO-0083 Quarry and Quarry Water Treatment Plant- December 1994
NRE-434-WS-PHO-0084 Construction
Photo Missing: Quarry Bulk Waste Removal
NRE-434-WS-PHO-0085 Quarry Transfer Station
NRE-434-WS-PHO-0086 Quarry Cleanup
NRE-434-WS-PHO-0087 Quarry Bulk Waste Removal 1995
NRE-434-WS-PHO-0088 Weldon Spring Quarry- May 1995
NRE-434-WS-PHO-0089 Haul Road Route

AV Box 2 cont.

NRE-434-WS-PHO-0090 Haul Road Underpass of Relocated Highway 94
NRE-434-WS-PHO-0091 Archeological Search of Prehistoric Indian Site along Haul Road Route
NRE-434-WS-PHO-0092 Construction Haul Road
NRE-434-WS-PHO-0093 Temporary Storage Area for Quarry Bulk Waste
NRE-434-WS-PHO-0094 Debris Consolidation in Vicinity of Temporary Storage Area
NRE-434-WS-PHO-0095 Building 437 during Demolition
NRE-434-WS-PHO-0096 Building 437 Dismantlement-Notice Use of Water for Dust Suppression
NRE-434-WS-PHO-0097 Building 438 Also in Footprint
NRE-434-WS-PHO-0098 Building 438-Dismantled in 1991, Making Way for Temporary Storage Area
NRE-434-WS-PHO-0099 Initial Grading for Temporary Storage Area
NRE-434-WS-PHO-0100 Liner Installation for Collection Basin of Temporary Storage Area

NRE-434-WS-PHO-0101 Temporary Storage Area Showing Liner Installation
NRE-434-WS-PHO-0102 Sand Placed on top of HDPE Temporary Storage Area Liner
NRE-434-WS-PHO-0103 Temporary Storage Area
NRE-434-WS-PHO-0104 TSA Transfer Station
NRE-434-WS-PHO-0105 Terex hauling truck at the TSA Transfer Station
NRE-434-WS-PHO-0106 Completed Temporary Storage Area
Photo Missing: TSA 1994
NRE-434-WS-PHO-0107 TSA December 1994
NRE-434-WS-PHO-0108 Temporary Storage Area May 1995
NRE-434-WS-PHO-0109 Deteriorating Condition of Barrels
NRE-434-WS-PHO-0110 Condition of Barrels at Site Prior to Chemical Consolidation Efforts
NRE-434-WS-PHO-0111 Chemicals Found in Buildings
NRE-434-WS-PHO-0112 Chemical Characterization
NRE-434-WS-PHO-0113 Chemical Consolidation
NRE-434-WS-PHO-0114 Building 434 Prior to Renovations for Chemical Storage
NRE-434-WS-PHO-0115 Building 434 1993
NRE-434-WS-PHO-0116 Building 434 Interior- Chemical Consolidation
NRE-434-WS-PHO-0117 Flammable Liquid Storage Buildings Being Set in Place
NRE-434-WS-PHO-0118 Flammable Liquid Storage Buildings
NRE-434-WS-PHO-0119 Magnesium Storage-Building 302
NRE-434-WS-PHO-0120 Magnesium Storage-Building 302 Dismantlement
NRE-434-WS-PHO-0121 Site Water Treatment Plant Pond Excavation
NRE-434-WS-PHO-0122 Completed Site Water Treatment Plant and Temporary Storage Area
NRE-434-WS-PHO-0123 Site Water Treatment Plant December 1994
NRE-434-WS-PHO-0124 Site Water Treatment Plant May 1995
NRE-434-WS-PHO-0125 Chemical Plant during Operational Period 1957-1966
NRE-434-WS-PHO-0126 Overhead Piping Asbestos Removal
NRE-434-WS-PHO-0127 Asbestos Hanging from Overhead Piping Causing Possible Health Threat to Workers
NRE-434-WS-PHO-0128 "Before" Photo of Buildings Showing Overhead Piping
NRE-434-WS-PHO-0129 "After" Photo of Buildings Showing Overhead Piping Removed
NRE-434-WS-PHO-0130 Transformers Leaking PCB Oils
NRE-434-WS-PHO-0131 PCB Transported Off-Site
NRE-434-WS-PHO-0132 Power Lines and Poles Prior to Removal
Photo Missing: Building 301 Prior to Dismantlement
NRE-434-WS-PHO-0133 Building 301 Interior
NRE-434-WS-PHO-0134 Building 301 Interior Cocoons
NRE-434-WS-PHO-0135 Removing Cocoon
NRE-434-WS-PHO-0136 Cocoon Removed
NRE-434-WS-PHO-0137 Building 301 Interior Work
NRE-434-WS-PHO-0138 Building 301 Interior during Dismantlement
NRE-434-WS-PHO-0139 Building 301 Interior after Interior Cleanup
NRE-434-WS-PHO-0140 Building Exterior Shot

AV Box 2 cont.

Photo Missing: Building 301 Dismantlement
NRE-434-WS-PHO-0141 Building 301 Dismantlement
NRE-434-WS-PHO-0142 Building 301 Dismantlement
NRE-434-WS-PHO-0143 Building Dismantlement
NRE-434-WS-PHO-0144 Building 201
NRE-434-WS-PHO-0145 Building 201 Plugging Holes for Negative Air Enclosure
NRE-434-WS-PHO-0146 201 Interior before Cleanup
NRE-434-WS-PHO-0147 201 Interior Remedial Activities
Photo Missing: Building 201 Dismantlement
NRE-434-WS-PHO-0148 Building 201 Dismantlement
NRE-434-WS-PHO-0149 Building Dismantlement
NRE-434-WS-PHO-0150 Building 201 Final Dismantlement January 1994
Photo Missing: Building 105 Dismantlement
Photo Missing: Building 103 Dismantlement
NRE-434-WS-PHO-0151 Building 406 before Dismantlement
NRE-434-WS-PHO-0152 Building 406 Slab
NRE-434-WS-PHO-0153 Equipment Dismantlement
Photo Missing: Removal of Train Engine
No NRE-434-WS-PHO-0154
NRE-434-WS-PHO-0155 Building Dismantlement Activities October 1993
NRE-434-WS-PHO-0156 Building Dismantlement Activities January 1994
NRE-434-WS-PHO-0157 Old St. Charles County Water Tower in Foreground, New
Water Tower in Back
Photo Missing: Water Tower July 1993
NRE-434-WS-PHO-0158 Water Tower July 1993
Photo Missing: Water Tower July 1993
NRE-434-WS-PHO-0159 Building 401-Steam Plant
NRE-434-WS-PHO-0160 Steam Plant Dismantlement
NRE-434-WS-PHO-0161 Conditions inside Steam Plant
NRE-434-WS-PHO-0162 After Interior Cleanup of Steam Plant
NRE-434-WS-PHO-0163 Asbestos Cleanup of Steam Plant
NRE-434-WS-PHO-0164 Negative Air Enclosure for Asbestos Cleanup of Building 401-
Steam Plant
NRE-434-WS-PHO-0165 Smoke Stack From Steam Plant Coming Down
NRE-434-WS-PHO-0166 Steam Plant Dismantlement
NRE-434-WS-PHO-0167 Second Phase of Steam Plant Dismantlement
Photo Missing: Steam Plant 1993
NRE-434-WS-PHO-0168 Steam Plant Dismantlement 1994
NRE-434-WS-PHO-0169 Building 101 Dismantlement March 1994
NRE-434-WS-PHO-0170 Ash Pond Diversion Dike 1993
NRE-434-WS-PHO-0171 Early Ash Pond Diversion Dike Construction
NRE-434-WS-PHO-0172 Re-Routing of Water around the Ash Pond
NRE-434-WS-PHO-0173 Vessels Containing TBP Mixed Waste
NRE-434-WS-PHO-0174 Tarp Covering Secondary Containment to Keep Out Rain

NRE-434-WS-PHO-0175 TBP Transfer to Drum Storage
NRE-434-WS-PHO-0176 TBP Tank Removal July 1994
NRE-434-WS-PHO-0177 Material Staging Area (MSA)
NRE-434-WS-PHO-0178 Material Staging Area Grading
NRE-434-WS-PHO-0179 Lining of Pond for Material Staging Area
NRE-434-WS-PHO-0180 Material Staging Area Phase I Grading for Phase II Started
NRE-434-WS-PHO-0181 Phase I and II of Material Staging Area Complete
NRE-434-WS-PHO-0182 Items Sorted in Material Staging Area
NRE-434-WS-PHO-0183 Reorganization of Building Debris on Material Staging Area
NRE-434-WS-PHO-0184 Dumping Ground
NRE-434-WS-PHO-0185 Material Staging Area 1993
NRE-434-WS-PHO-0186 Material Staging Area

AV Box 2 cont.

NRE-434-WS-PHO-0187 Material Staging Area December 1994
NRE-434-WS-PHO-0188 Material Staging Area May 1995
NRE-434-WS-PHO-0189 Raffinate Pits December 1994
NRE-434-WS-PHO-0190 Bionitrification of Raffinate Pits
NRE-434-WS-PHO-0191 Denitrification process
NRE-434-WS-PHO-0192 Chemical Stabilization/Solidification (CSS) Pilot Plant—May 1995
NRE-434-WS-PHO-0193 Weldon Spring Borrow Area- February 1994
NRE-434-WS-PHO-0194 The Borrow Area May 1995
NRE-434-WS-PHO-0195 Aerial View
NRE-434-WS-PHO-0196 View Inside Sea-Land Containers Where Asbestos is Stored
NRE-434-WS-PHO-0197 Mobile Water Treatment Plant
NRE-434-WS-PHO-0198 Mobile Water Treatment Plant
NRE-434-WS-PHO-0199 Administration Building Prior to Dismantlement
NRE-434-WS-PHO-0200 Administration Building Demolition
NRE-434-WS-PHO-0201 Administration Building Demolition
NRE-434-WS-PHO-0202 Administration Building Slab
NRE-434-WS-PHO-0203 Administration Building Slab Demolition
NRE-434-WS-PHO-0204 Composite Building Construction at Site of Old Administration Building
NRE-434-WS-PHO-0205 Old Access Control
NRE-434-WS-PHO-0206 New Access Control/Composite Building 1993
NRE-434-WS-PHO-0207 Construction Worker in PCM
NRE-434-WS-PHO-0208 Aerial Showing Proximity of Francis Howell High School to Site
Photo Missing: Weldon Spring Site December 1993
NRE-434-WS-PHO-0209 Weldon Spring Site December 1994
NRE-434-WS-PHO-0210 Weldon Spring Site Surrounded by Busch and Weldon Spring Conservation Area
NRE-434-WS-PHO-0211 Weldon Spring Site May 1995
NRE-434-WS-PHO-0212 Aerial View
NRE-434-WS-PHO-0213 Conceptual Disposal Facility

NRE-434-WS-PHO-0214 Men engaged in cleanup activities

AV Box 3

NRE-434-WS-PHO-0215 Muddy Lot
NRE-434-WS-PHO-0216 Site Water Treatment Plant
NRE-434-WS-PHO-0217 Site Water Treatment Plant
NRE-434-WS-PHO-0218 Haul Road in Final Stages of Construction
NRE-434-WS-PHO-0219 Quarry Water Treatment Plant Interior
NRE-434-WS-PHO-0220 Quarry Transfer Station Construction
NRE-434-WS-PHO-0221 Map of Quarry Bulk Waste Haul Road
NRE-434-WS-PHO-0222 Haul Road Underpass of Relocated Highway 94
NRE-434-WS-PHO-0223 Archeological Search of Prehistoric Indian Site along Haul Road Route
NRE-434-WS-PHO-0224 Liner Installation for Collection Basin of Temporary Storage Area
NRE-434-WS-PHO-0225 Temporary Storage Area
NRE-434-WS-PHO-0226 Foot of Sand Placed on Top of HDPE Temporary Storage Area Liner
NRE-434-WS-PHO-0227 Storage Containers
NRE-434-WS-PHO-0228 Quarry Water Treatment Plant Interior
NRE-434-WS-PHO-0229 Dumping Ground
NRE-434-WS-PHO-0230 Building 301 Dismantlement Activities
NRE-434-WS-PHO-0231 Haul Road in Final Stages of Construction
NRE-434-WS-PHO-0232 Demonstration of the Temporary Storage Area Transfer Station
NRE-434-WS-PHO-0233 Quarry Transfer Station Construction
NRE-434-WS-PHO-0234 St. Charles County Well Field
NRE-434-WS-PHO-0235 Conceptual Treatment System
NRE-434-WS-PHO-0236 Quarry Dump and Cover Operations in the Late 50's and 60's

AV Box 3

NRE-434-WS-PHO-0237 Weldon Spring Quarry 1993 Three Million Gallons of Water
NRE-434-WS-PHO-0238 Demonstration of the Temporary Storage Area Transfer Station
NRE-434-WS-PHO-0239 Completed Temporary Storage Area
NRE-434-WS-PHO-0240 Old St. Charles County Water Tower in Foreground, New Water Tower in Back
NRE-434-WS-PHO-0241 Building 437 Dismantlement
NRE-434-WS-PHO-0242 Ash Pond Diversion Dike 1993
NRE-434-WS-PHO-0243 Early Ash Pond Diversion Dike Construction
NRE-434-WS-PHO-0244 Re-Routing of Water around the Ash Pond
NRE-434-WS-PHO-0245 Mobile Water Treatment Plant
NRE-434-WS-PHO-0246 Composite Building Construction at Site of Old Administration Building
NRE-434-WS-PHO-0247 Administration Building Slab Demolition
NRE-434-WS-PHO-0248 Material Staging Area
NRE-434-WS-PHO-0249 Building 437 during Demolition
NRE-434-WS-PHO-0250 Second Phase of Steam Plant Dismantlement

NRE-434-WS-PHO-0251 Steam Plant Dismantlement
NRE-434-WS-PHO-0252 Smoke Stack from Steam Plant Coming Down
NRE-434-WS-PHO-0253 Asbestos Cleanup of Steam Plant
NRE-434-WS-PHO-0254 Building 401- Steam Plant
NRE-434-WS-PHO-0255 After Interior Cleanup of Steam Plant
NRE-434-WS-PHO-0256 Site Water Treatment Plant Pond Excavation
NRE-434-WS-PHO-0257 Initial Grading for Temporary Storage Area
NRE-434-WS-PHO-0258 Temporary Storage Area Showing Liner Installation
NRE-434-WS-PHO-0259 Aerial Showing Proximity of Francis Howell High School to Site
NRE-434-WS-PHO-0260 Items Sorted in Material Staging Area
NRE-434-WS-PHO-0261 Crane lowering trailer into place
NRE-434-WS-PHO-0262 Tarp Covering Secondary Containment to Keep Out Rain
NRE-434-WS-PHO-0263 TBP Transfer to Drum Storage
NRE-434-WS-PHO-0264 Old Access Control
NRE-434-WS-PHO-0265 New Access Control/Composite Building 1993
NRE-434-WS-PHO-0266 PCB Transported Off-Site
NRE-434-WS-PHO-0267 Mobile Water Treatment Plant
NRE-434-WS-PHO-0268 “After” Photo of Buildings Showing Overhead Piping Removed
NRE-434-WS-PHO-0269 Material Staging Area Grading
NRE-434-WS-PHO-0270 Lining of Pond for Material Staging Area
NRE-434-WS-PHO-0271 Material Staging Area Phase I Grading for Phase II Started
NRE-434-WS-PHO-0272 Condition of Barrels at Site Prior to Chemical Consolidation Efforts
NRE-434-WS-PHO-0273 Chemical Characterization
NRE-434-WS-PHO-0274 Building 434 Prior to Renovations for Chemical Storage
NRE-434-WS-PHO-0275 Building 434 1993
NRE-434-WS-PHO-0276 Vessels Containing TBP Mixed Waste
NRE-434-WS-PHO-0277 Completed Site Water Treatment Plant and Temporary Storage Area
NRE-434-WS-PHO-0278 Site Water Treatment Plant Pond Excavation
NRE-434-WS-PHO-0279 Temporary Storage Area Prior to Grading
NRE-434-WS-PHO-0280 Negative Air Enclosure for Asbestos Cleanup of Building 401- Steam Plant
NRE-434-WS-PHO-0281 Steam Plant Dismantlement
NRE-434-WS-PHO-0282 Building 438 Dismantled in 1991 Making Way for the Temp. Storage Area
NRE-434-WS-PHO-0283 Building 438 Also in Footprint
NRE-434-WS-PHO-0284 Quarry Water Treatment Plant Construction- Spring ‘91
NRE-434-WS-PHO-0285 Haul Road Construction
NRE-434-WS-PHO-0286 Secondary Containment for TBP
NRE-434-WS-PHO-0287 Chemicals Found in Buildings
NRE-434-WS-PHO-0288 Deteriorating Conditions of Barrels
NRE-434-WS-PHO-0289 Building

AV Box 3 cont.

NRE-434-WS-PHO-0290 Administration Building Prior to Dismantlement
NRE-434-WS-PHO-0291 Administration Building Demolition
NRE-434-WS-PHO-0292 Conceptual Treatment System
NRE-434-WS-PHO-0293 Overhead Piping Asbestos Removal
NRE-434-WS-PHO-0294 Building 301 Interior Cocoons
NRE-434-WS-PHO-0295 Building 301 Interior
NRE-434-WS-PHO-0296 Building 201- Plugging Holes for Negative Air Enclosure
NRE-434-WS-PHO-0297 Building 301- Interior after Cleanup
NRE-434-WS-PHO-0298 Cocoon Removed
NRE-434-WS-PHO-0299 Removing Cocoon
NRE-434-WS-PHO-0300 Site Water Treatment Plant Pond Excavation
NRE-434-WS-PHO-0301 Crane lowering trailer into place
NRE-434-WS-PHO-0302 Haul Road Construction
NRE-434-WS-PHO-0303 Secondary Containment for TBP
NRE-434-WS-PHO-0304 Temporary Storage Area Prior to Grading
NRE-434-WS-PHO-0305 Quarry Water Treatment Plant Liner Installation
NRE-434-WS-PHO-0306 Water Treatment System Schematic
NRE-434-WS-PHO-0307 Cooling Tower Building 413
NRE-434-WS-PHO-0308 Dismantlement of Cooling Tower
NRE-434-WS-PHO-0309 5/3/93 TBP
NRE-434-WS-PHO-0310 Magnesium Storage- Building 302 Dismantlement
NRE-434-WS-PHO-0311 Magnesium Storage- Building 302
NRE-434-WS-PHO-0312 Administration Building Demolition
NRE-434-WS-PHO-0313 Building 406 before Dismantlement
NRE-434-WS-PHO-0314 Building 406 Slab
NRE-434-WS-PHO-0315 Material Staging Area (MSA)
NRE-434-WS-PHO-0316 Material Staging Area 1993
NRE-434-WS-PHO-0317 Aerial View
NRE-434-WS-PHO-0318 Three Buildings and a Vehicle
Photo Missing: Borrow Area-Undated
NRE-434-WS-PHO-0319 Large Pit
Photo Missing: Borrow Area-Undated
NRE-434-WS-PHO-0320 Weldon Spring Site May 1995
NRE-434-WS-PHO-0321 Aerial View of Buildings
NRE-434-WS-PHO-0322 Two Men in Water Area
NRE-434-WS-PHO-0323 Crane lowering large cylinder
NRE-434-WS-PHO-0324 Water Tower July 1993
NRE-434-WS-PHO-0325 Water Tower
NRE-434-WS-PHO-0326 Water Tower July 1993
NRE-434-WS-PHO-0327 Water Tower
NRE-434-WS-PHO-0328 Water Tower July 1993
NRE-434-WS-PHO-0329 Water Tower
NRE-434-WS-PHO-0330 Old St. Charles County Water Tower in Foreground, New
Water Tower in Back
NRE-434-WS-PHO-0331 Water Tower

NRE-434-WS-PHO-0332 Water Tower and Wrecking Equipment
NRE-434-WS-PHO-0333 Weldon Spring Site Remedial Action Project
NRE-434-WS-PHO-0334 WSSRAP Critical Success Factors
NRE-434-WS-PHO-0335 Weldon Spring Quarry May 1995
NRE-434-WS-PHO-0336 Quarry Bulk Waste Removal November 1995
NRE-434-WS-PHO-0337 Quarry Dump and Cover Operations in the Late 50's and 60's
NRE-434-WS-PHO-0338 1988 Quarry Aerial
NRE-434-WS-PHO-0339 Weldon Spring Quarry and Quarry Water Treatment Plan-
Dec. 1994
NRE-434-WS-PHO-0340 Quarry Bulk Waste Removal

AV Box 3 Cont.

NRE-434-WS-PHO-0341 Building 434 Prior to Renovations for Chemical Storage
NRE-434-WS-PHO-0342 Dumping Ground
NRE-434-WS-PHO-0343 Building Being Dismantled
NRE-434-WS-PHO-0344 Building in Construction Site
NRE-434-WS-PHO-0345 Building 201 Dismantlement
NRE-434-WS-PHO-0346 Administration Building Slab Demolition
NRE-434-WS-PHO-0347 Aerial View of Site
NRE-434-WS-PHO-0348 Building 105 Dismantlement
NRE-434-WS-PHO-0349 Building 437 Dismantlement
NRE-434-WS-PHO-0350 Containerized Chemicals in Building 434
NRE-434-WS-PHO-0351 Site Water Treatment Plant Pond Excavation
NRE-434-WS-PHO-0352 Quarry Water Treatment Plant Interior
NRE-434-WS-PHO-0353 Weldon Spring Quarry 1993
NRE-434-WS-PHO-0354 Construction Shot
NRE-434-WS-PHO-0355 Mobile Water Treatment Plant
NRE-434-WS-PHO-0356 Aerial View of Pond
NRE-434-WS-PHO-0357 TSA Transfer Station
NRE-434-WS-PHO-0358 Aerial View
NRE-434-WS-PHO-0359 Chemical Plant during Operational Period
NRE-434-WS-PHO-0360 Quarry Transfer Station
NRE-434-WS-PHO-0361 Construction
NRE-434-WS-PHO-0362 Material Staging Area
NRE-434-WS-PHO-0363 Completed Temporary Storage Area
NRE-434-WS-PHO-0364 Building 434 1993
NRE-434-WS-PHO-0365 Weldon Spring Quarry and Quarry Water Treatment
NRE-434-WS-PHO-0366 Weldon Spring Quarry April 1994
NRE-434-WS-PHO-0367 Aerial of the Site Water Treatment Plant
NRE-434-WS-PHO-0368 Weldon Spring Quarry May 1995
NRE-434-WS-PHO-0369 Quarry Water Treatment Plant Construction- Spring 1991
NRE-434-WS-PHO-0370 Quarry Bulk Waste Removal 1993-1995 Collage of Images
NRE-434-WS-PHO-0371 Overhead Piping Asbestos Removal
NRE-434-WS-PHO-0372 View Inside Sea-Land Containers Where Asbestos is Stored
NRE-434-WS-PHO-0373 "After" Photo of Buildings Showing Overhead Piping
Removed

NRE-434-WS-PHO-0374 “Before” Photo of Buildings Showing Overhead Piping
NRE-434-WS-PHO-0375 TBP Transfer to Drum Storage
NRE-434-WS-PHO-0376 Asbestos Hanging from Overhead Piping Causing Possible Health Threat
NRE-434-WS-PHO-0377 Magnesium Storage Building 302 Dismantlement
NRE-434-WS-PHO-0378 Magnesium Storage Building 302
NRE-434-WS-PHO-0379 Negative Air Enclosure for Asbestos Cleanup of Building 401- Steam Plant
NRE-434-WS-PHO-0380 Asbestos Containing Material Storage Area
NRE-434-WS-PHO-0381 Site Water Treatment Plant Pond Excavation
NRE-434-WS-PHO-0382 Quarry Water Treatment Plant- 1993
NRE-434-WS-PHO-0383 Building Interior
NRE-434-WS-PHO-0384 Asbestos Cleanup of Steam Plant
NRE-434-WS-PHO-0385 Aerial View
NRE-434-WS-PHO-0386 Weldon Spring Uranium Feed Materials Plant
NRE-434-WS-PHO-0387 Weldon Spring Site December 1993
NRE-434-WS-PHO-0388 TSA 1994
NRE-434-WS-PHO-0389 Aerial View
NRE-434-WS-PHO-0390 Backhoe and Dump truck
NRE-434-WS-PHO-0391 Dump truck and Backhoe
NRE-434-WS-PHO-0392 Cleanup of Dumping Ground
NRE-434-WS-PHO-0393 Cleanup with hose
NRE-434-WS-PHO-0394 Whole Body Monitors Access Control
NRE-434-WS-PHO-0395 Negative Air Enclosure
NRE-434-WS-PHO-0396 Building 201 Interior Cleanup
NRE-434-WS-PHO-0397 Building Exterior
NRE-434-WS-PHO-0398 Building Interior
NRE-434-WS-PHO-0399 Building Exterior by Construction Site
NRE-434-WS-PHO-0400 Building 201 Dismantlement Activities
NRE-434-WS-PHO-0401 Building during Dismantlement
NRE-434-WS-PHO-0402 Building 201
NRE-434-WS-PHO-0403 Building 201 Interior